## CORE CREDIT TAG / CORE RETURN AUTHORIZATION CORE DUE DATE: 04-09-2015

SALES ORDER NO:

5956912

TYPE OF SERVICE:

**ER04 HAPP/MPP Programs** ( ZXFC FOC Item Exchange )

DATE SHIPPED:

03-26-2015

CHECK CORRECT TYPE OF RETURN:

□Warranty Core □Unused Return for Credit

□Exchange Core □Customer Repair

□Rental Return

□Out of Box Failure/Dead On Arrival(DOA)

## THIS FORM MUST BE COMPLETED AND RETURNED TO RECEIVE CORE CREDIT

CUSTOMER INFORMATION: PRO STAR AVIATION 5 INDUSTRIAL DR LONDONDERRY NH 03053

CUSTOMER SHIP TO ADDRESS: TURBINE ENGINE SPECIALISTS INC 3804 FALCON WAY W 18S FORT WORTH TX 76106

USA

PART INSTALLED:

PART NO: SERIAL NO:

7021450-801 04105183

MODEL:

**RCVR - TRANSMITTER - ANTENNA** 

AIRCRAFT INFORMATION:

A/C TYPE:

FAL900B

A/C SERIAL NO:

87

		THE PROPERTY OF	TAIL NO.	VQ-BZZ		
PART REMOVE	D:					
PART NO: SERIAL NO: A/C HOURS: UNIT HOURS:	7021450-801	REPLACEMENT S	OLVED PROBLEM? (	Yes or No)		
DESCRIPTION		WE ARE T	ZETURNING	THES 6	EXCHANGE	1240A72
	UND	POVED. WE	CANNOT	INST	ALL THE	5
-	UNIT	BELAUSÉ I	T IS TH	le same	= S/N AS	
	UST	TIME.				
-	* THE	SEXVILLE REPOR	T 32027	4219 F	AS THE	
	CORRE	CT (LONGTATL) TEX	T AND THE	whomas	ATRPLANE.	WHY?
T Se	O OUR KNOWLEDGE EVERE STRESS, HEA	E, THE ABOVE REFERENCED PA T OR FLUID INGRESS (AS IN MA	RT(S) OR MATERIAL JOR ENGINE FAILUR	WAS/WERE NOT E, ACCIDENT, INC	SUBJECTED TO	
SIGNATURE/CO	MPLETED BY:	Tallo (All Ly Company Representative	TELEPH	ONE NO:	1784501	45

	Company Represe
MAINTENANCE CONTRACT:	⊥ HAP
TYPE:	
HOUGY WELL	ASB #
HOUSYWELL 0	295

SHIP REPAIRABLE UNIT TO:

Wichita Service Center Honeywell International Inc 7227 W. Harry WICHITA KS 67209

BILLABLE RENTALS ARE INVOICED AT THE ONE MONTH MINIMUM RENTAL FEE AT THE TIME OF SHIPMENT. NO CHARGE AND BILLABLE RENTAL RETURNS WILL BE REVIEWED AND LATE RETURN FEES WILL BE ACCESSED AND INVOICED ON THE SAME P.O. CORE RETURN POLICY ON PAGE 2.

	88	×	88	88	88	900		888		w	300		98	888	888	11111	200	987	80	88	880	800		888	988	388	886	
œ	ж	×	•	m	12		14	n	: 18	880	70	72	12	17		198		м	-	•	20	7	m	SX	22	223	en:	
M	м	3		,,,		90	44	40	4	200	344	w	ш	88	e.	200	38.	n	м.	ы.	м		LA.	81	ж	311	€8	R

HONEYWELL CONTACT: CORE RECOVERY TEAM

TEL:480-353-4615

EMAIL: CORERECOVERYINTEAM@HONEYWELL.COM

TEL:1-800-239-8943

WEBSITE: WWW.MYAEROSPACE.COM

## **Honeywell**

## **SERVICE REPORT**

M&PM Assets

Honeywell Inc. Wichita Service Center 7227 W. Harry WICHITA KS 67209

SR NUMBER: 3	20274219 50	08290508		TEL:	01-3099	FAX: 316-522-2693				
PO:		CUSTOMER PART NUMBER:			BER:					
DATE REJECTED:										
17 FEB 2015		DATE RECEIVED: 26 FEB 2015		DATE COMPLETED: 05 MAR 2015						
A/C TYPE: GIV		A/C TAIL NUMBER:		A/C SERIAL NUMBER:						
PACKING STATUS:		SEALS INTACT:			PHYSICAL DAMAGE: NO DAMAGE FOUND					
		EXACT MALFUNCTION THAT R/T C/	AME IN W	C						
	AS RECEIVED:		AS REL	EASE	D:					
PART NUMBER	7021450-801		70214	50-801						
DESCRIPTION:	RCVR - TRANSMITTER	- ANTENNA ASSEMBLY	RCVR	RCVR - TRANSMITTER - ANTENNA ASSEMBLY						
SERIAL NUMBER:	04105183	X	04105183							
UCN/SER:	04105183		04105183							
HW MOD STATUS:	A-P,S-U,W,Y		A-P,S-	Y		,				
SW MOD STATUS:										
SOFTWARE LOAD:										
REASON FOR REMOVA	AL CONFIRMED: Failure N	ot Related To Rejection	ESTIMATE SUPPLIED: no							
PRIMARY SHOP FINDIN	NG: Fault Found But Uncorr	related Removal	WARRANTY: Partial Warranty Granted							
TYPE OF SERVICE: Re	epaired And Modified	TECHNICIAN: Carl Losey								
MAINTENANCE STATEMENT: PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2										
SIGNATURE BELOW RI	EQUIRED ONLY WHEN RE	TURN TO SERVICE IS NOT ISSUED:								
SIGNATURE OF AUTHORIZED PERSON: DATE:										
SHOULD YOU REQUIRE RESPONSE	E ANY FURTHER INFORMATION CENTER AT 1-800-601-3099 O	N REGARDING THIS SERVICE REPORT, R VISIT OUR CUSTOMER PORTAL AT W	OR HAVE	ANY Q	UESTIONS, PLEASE O	ONTACT OUR CUSTOMER AN INQUIRY.				

PAGE:1 of 2