



Longtail Aviation International, Ltd. - Phone: +1 441 293 5971, Fax: +1 441 293 5972 - 4/2/2015 2:34:04 PM
Repair Station #: BDA/AMO/241 - 6 Southside Road, St George Parish, DD03 Bermuda

Maintenance Work Order

A/C Reg. Number: VQ-BZZ	A/C S/N: 087	Year, Make, Model: Dassault Falcon 900B	Work Order #: 0487-01-2014	ACTT: 10629
Item: 58	Date: 01/29/2014	ATA: 34-21-00-710-801	Landings: 4146	

Discrepancy:

LH ATTITUDE INDICATOR FAILS INTERMITTENTLY AND ADI SCREEN GOES TO FULL BLUE INTERMITTENTLY. LH ATT FAIL ANNUNCIATOR AND RH COMPARATOR CONFIRMS

WAS THIS A INCOMING
"C" CHECK SQUAWK??
TODD.

Corrective Action:

SWAPPED #1 AND #2 INERTIAL REFERENCE UNIT'S FOR TROUBLESHOOTING AS FOLLOWS:

#1 IRU (L2FP), P/N: HG1075AE03, IS NOW S/N: 906 (34-21-01-900-801-01).

#2 IRU (R2FP), P/N: HG1075AE03 IS NOW S/N 706 (34-21-01-900-801-02).

PERFORMED OPERATIONAL TEST OF THE INERTIAL REFERENCE SYSTEM (IRS) I.A.W. F900B AMM 34-21-00-710-801. OPS CHECKED GOOD.

Mechanic Signature:	Certification #:	Date:	Inspector Signature:	Certification #:	Date:
---------------------	------------------	-------	----------------------	------------------	-------