



Longtail Aviation International, Ltd. - Phone: +1 441 293 5971, Fax: +1 441 293 5972 - 4/1/2015 4:26:28 PM
Repair Station #: BDA/AMO/241 - 6 Southside Road, St George Parish, DD03 Bermuda

Maintenance Work Order

A/C Reg. Number: VQ-BZZ	A/C S/N: 087	Year, Make, Model: Dassault Falcon 900B	Work Order #: 0557-07-2014	ACTT: 10783.4
Item: 5	Date: 07/30/2014	ATA:	Landings: 4213	

Discrepancy:

RADAR GIVING GHOST INDICATIONS IN NORMAL FLIGHT.

TLP = 0589 AFHS = 10783.4 LNDS = 4213 APU = 2494.5

Corrective Action:

REMOVED DEFECTIVE RTA P/N 7021450-801 S/N 1010B446 AND INSTALLED A REPAIRED RTA P/N 7021450-801 S/N 04105183 I.A.W F900B M.M 34-41-01-900-801

TLP = 0589 AFHS = 10783.4 LNDS = 4213 APU = 2494.5

Mechanic Signature:	Certification #:	Date:	Inspector Signature:	Certification #:	Date:
---------------------	------------------	-------	----------------------	------------------	-------