



Longtail Aviation International, Ltd. - Phone: +1 441 293 6971, Fax: +1 441 293 6972 - 4/1/2015 4:31:27 PM
Repair Station #: BDA/AMO/241 - 6 Southside Road, St George Parish, DD03 Bermuda

Maintenance Work Order

A/C Reg. Number: VQ-BZZ	A/C S/N: 087	Year, Make, Model: Dassault Falcon 900B	Work Order #: 0636-02-2015	ACTT: 10923.5
Item: 5	Date: 03/02/2015	ATA:	Landings: 4251	

Discrepancy:

WEATHER RADAR WILL NOT PAINT 10-50 NM .

Corrective Action:

REMOVED DEFECTIVE RADAR R/T P/N 7021450-801 S/N 04105183 AND INSTALLED REPAIRED R/T P/N 7021450-801 S/N 99021268 I.A.W THE F900B M.M 34-41-01-900-801.

Mechanic Signature:	Certification #:	Date:	Inspector Signature:	Certification #:	Date:
---------------------	------------------	-------	----------------------	------------------	-------