



Longtail Aviation International, Ltd. - Phone: +1 441 293 5971, Fax: +1 441 293 5972 - 4/1/2015 6:15:17 PM
Repair Station #: BDA/AMO/241 - 6 Southside Road, St George Parish, DD03 Bermuda

Maintenance Work Order

A/C Reg. Number: VQ-BZZ	A/C S/N: 087	Year, Make, Model: Dassault Falcon 900B	Work Order #: 0487-01-2014	ACTT: 10629
Item: 57	Date: 01/18/2014	ATA: 53-11-01-900-801-01	Landings: 4146	

Discrepancy:

RADAR GIVES GHOST RETURN IN CLEAR AIR SINCE RADOME WAS REPAINTED BY DUNCAN AVIATION.

VERIFIED COMPLAINT

REMOVED NOSE CONE AND SHIPPED TO APPLIED AERODYNAMICS, INC. FOR EVALUATION. TRANSMISSION TEST RESULTS FAR BELOW DASSAULT ACCEPTABLE LEVELS

Corrective Action:

REMOVED NOSE CONE, P/N: FGFB208B1, S/N: BZ160, AND SHIPPED TO DUNCAN AVIATION LINCOLN FOR REPAINT/EVALUATION. INSTALLED EXCHANGED REPAIRED NOSE CONE ASSEMBLY, P/N: FGFB208B1, S/N: BZ165, AFTER DUNCAN AVIATION REPAINT. ALL WORK DONE I.A.W. F900B AMM 53-11-01-900-801-01. OPS CHECKED RADAR.

BZ165 NOW ON AIRCRAFT

Mechanic Signature:	Certification #:	Date:	Inspector Signature:	Certification #:	Date:
---------------------	------------------	-------	----------------------	------------------	-------