

SERVICE REPORT

M&PM Assets

Honeywell Inc.
Wichita Service Center
7227 W. Harry
WICHITA KS 67209

SR NUMBER: 320274219		5008290508	TEL: 800-601-3099	FAX: 316-522-2693
PO: 0	CUSTOMER PART NUMBER:		CONTRACT NUMBER:	
DATE REJECTED: 17 FEB 2015	DATE RECEIVED: 26 FEB 2015		DATE COMPLETED: 05 MAR 2015	
A/C TYPE: GIV	A/C TAIL NUMBER: N119FM		A/C SERIAL NUMBER: 1464	
PACKING STATUS:	SEALS INTACT: Yes		PHYSICAL DAMAGE: NO DAMAGE FOUND	
REASON FOR REMOVAL: RADAR FAILS TO PAINT 10-50NM. THIS IS THE EXACT MALFUNCTION THAT R/T CAME IN WITH REPAIR PAPERWORK 7 MONTHS AGO. ARE WE DOING REPAIR TEST EFFECTIVELY?				

COPY

	AS RECEIVED:	AS RELEASED:
PART NUMBER	7021450-801	7021450-801
DESCRIPTION:	RCVR - TRANSMITTER - ANTENNA ASSEMBLY	RCVR - TRANSMITTER - ANTENNA ASSEMBLY
SERIAL NUMBER:	04105183	04105183
UCN/SER:	04105183	04105183
HW MOD STATUS:	A-P,S-U,W,Y	A-P,S-Y
SW MOD STATUS:		
SOFTWARE LOAD:		

REASON FOR REMOVAL CONFIRMED: Failure Not Related To Rejection	ESTIMATE SUPPLIED: no
PRIMARY SHOP FINDING: Fault Found But Uncorrelated Removal	WARRANTY: Partial Warranty Granted
TYPE OF SERVICE: Repaired And Modified	TECHNICIAN: Carl Losey

MAINTENANCE STATEMENT:
PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2

SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED:

SIGNATURE OF AUTHORIZED PERSON: _____ **DATE:** _____

SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT WWW.MYAEROSPACE.COM TO SUBMIT AN INQUIRY.