



Longtail Aviation International, Ltd. - Phone: +1 441 293 6971, Fax: +1 441 293 6972 - 4/1/2016 6:12:39 PM
Repair Station #: BDA/AMO/241 - 6 Southside Road, St George Parish, DD03 Bermuda

Maintenance Work Order

A/C Reg. Number: VQ-BZZ	A/C S/N: 087	Year, Make, Model: Dassault Falcon 900B	Work Order #: 0393-07-2013	ACTT: 1349.1
Item: 22	Date: 08/12/2013	ATA:	Landings: 4052	

Discrepancy:

OBSERVED LIGHTNING STRIKE MINOR DAMAGE ON RADOME UPPER RIGHT QUADRANT WHILE PERFORMING BASIC INSPECTION.

WORK DONE 07-JULY-2013

TLP=0443 AFHS=10349.1 LNDGS=4050 APU 2254

Corrective Action:

REMOVED LIGHTNING DAMAGED NOSE CONE RADOME P/N FGFB208B1 S/N BZ227 INSTALLED REPAIRED RADOME P/N FGFB208B1 S/N BZ160. WORK IAW 53-11-01900-801
RADOME COST AND SHIPPING TO BE ADDED TO AUGUST WO

WORK DONE 07-JULY-2013

TLP=0443 AFHS=10349.1 LNDGS=4050 APU 2254

← DFJ EXCHANGE
WE FLEW THIS RADOME
SEVERAL MONTHS WITH
NO STRIPES.

Mechanic Signature:	Certification #:	Date:	Inspector Signature:	Certification #:	Date:
---------------------	------------------	-------	----------------------	------------------	-------